


To the left: SLT latch

To the right: the schematic for this SLT

Details of the SLT reparation problem

The SLT card (right hand picture) shows, among other parts, the 16 latches used for caching the printer data. The latch labeled no. 6 is defect.

After removing the SLT case, one can see the discrete transistor and diode units with a magnifier. The resistances at the back of the ceramic-makers are not accessible. Now we can replace faulty transistors by standard transistors on the back of the SLT card.



SLT-Card 4628